

Babytherm 8004 / 8010

Technical Service Bulletin # 2

Re: Retrofitting of additional inner flaps

Update: May 31, 2000

Reference Doc: IDM no. 2 / 04.2000

Reason: It has been determined that it is possible for patients to force open the side flaps of the Babytherm and fall out of the unit when the side flaps are not locked properly.

Solution:

1. We request all our Customers to always use the additional inner flaps of the Babytherm 8000 / 8004 / 8010 in the future to exclude any risk of the patient falling out through open side flaps. We have amended the relevant section of the Operating Instructions, which currently recommends the optional use of the inner flaps for particularly lively patients, to recommend use of inner flaps for all patients at all times.
2. If the User choose not to use the inner flaps, in particular he or she must ensure that side flaps are locked correctly.
3. As of January 2000 all new Babytherms 8000 / 8004 / 8010 will be produced with inner flaps.

Devices affected: All units without inner flaps.

When: At next Service Call or Preventive Maintenance.

Additional Info: If you find a Babytherm 8000 / v8004 / 8010 without inner flaps proceed as follows:

- Hand the Customer a copy of the TSB Babytherm 8004 / 8010 # 2 and of the TSB Babytherm 8000 # 7.
- Request the Customer to order the inner flaps or offer to order them for the Customer.
- Inform the User that he/she must take special precautions until the ordered inner flaps have arrived. If the User choose not to use the inner flaps, in particular he or she must ensure that side flaps are locked correctly.

- Record that you have instructed the user stating the name of the person instructed, and attempt to obtain his/her signature on the PMS Checklist Form / Test Certificate.

This TSB is identical to [TSB Babytherm 8000 # 7](#).

Cost: Covered by Customer.

Ordering Info: Order 2 pieces for one units:
Inner flap P/N 2M 20 936

Distribution: Dräger Service Personnel and Authorized Service Organizations for CCS products.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789

Dräger Medical, Inc.
Technical Product Manager